

Inspection Photos

August 1st, 2025

Operator: Benson Montin and Greer

Location ID: 325307

Inspection Document #: 714002351

La Plata County, CO

Township: SENW 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

August 1, 2025
316° NW



Inspection Photos

Location Name: La Posta Canyon 2

Location ID: 325307



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos

Location Name: La Posta Canyon 2

Location ID: 325307



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west.

Inspection Photos

Location Name: La Posta Canyon 2

Location ID: 325307



August 1, 2025
306° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Patch of flowering Musk Thistle observed at the reclaimed well pad.

API #: 067-06135

Inspection Photos

Location Name: La Posta Canyon 2

Location ID: 325307

August 1, 2025
114° SE



Photo 5. View of recently reclaimed access road taken from the starting point facing south towards reclaimed well pad.

Inspection Photos
Location Name: La Posta Canyon 2
Location ID: 325307

August 1, 2025
4° N



Photo 6. View of reference area composed of Smooth Brome, Indian Ricegrass, Sagebrush and Juniper.