

Inspection Photos
Location Name: Milton H. Nelson B1
Location ID: 336292



Photo 1 Location.



Photo 2 Unused pump jack.

Inspection Photos
Location Name: Milton H. Nelson B1
Location ID: 336292



Photo 3 ancillary equipment.

Photo 4 location.

Inspection Photos
Location Name: Milton H. Nelson B1
Location ID: 336292



Photo 5 Unused pump jack in tall vegetation.

Photo 6 Well site sign covered by vegetation.

Inspection Photos
Location Name: Milton H. Nelson B1
Location ID: 336292



Photo 7 Wellhead over grown with vegetation.

Photo 8 Wellsite sign covered by vegetation.