

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0927 Entrance to location



Photo # 0937 Battery sign contains inaccurate nearest public road information

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025




Photo # 0929 Location



Photo # 0935 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0993 NW corner of location



Photo # 0994 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0995 SE corner of location



Photo # 0996 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0931 Wellhead sign lacks required information

Photo # 0963 Failure to minimize erosion & transport of sediment - Erosion & transport of sediment on cutslope/sediment migrating onto location/insufficient BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



**Photo # 0964 Failure to minimize erosion & transport of sediment
- Erosion & transport of sediment on cutslope/sediment migrating
onto location/insufficient BMP's**

**Photo # 0966 Failure to minimize erosion & transport of sediment
- Erosion & transport of sediment on cutslope/sediment migrating
onto location/insufficient BMP's**

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0968 Failure to minimize erosion & transport of sediment



Photo # 0970 Failure to minimize erosion & transport of sediment

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 0977 Tunnel erosion/Berm needs maintenance



Photo # 0982 Tunnel erosion/Berm needs maintenance

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 07/29/2025



Photo # 1002 Failure to minimize erosion & transport of sediment



Photo # 1004 Debris