

Inspection Photos
Location Name: Suckla G unit 1
Location ID: 317830



Photo 1 Location.

Photo 2 Location.

Inspection Photos
Location Name: Suckla G unit 1
Location ID: 317830



Photo 3 Wellhead in tall vegetation.



Photo 4 Ancillary Equipment in tall vegetation.

Inspection Photos
Location Name: Suckla G unit 1
Location ID: 317830



Photo 5 Wellhead in tall vegetation.

Photo 6 Horizontal Heated Separator in tall vegetation.

Inspection Photos
Location Name: Suckla G unit 1
Location ID: 317830



Photo 7 Flow line manifold in tall vegetation.

Photo 8 Tank battery sign.

Inspection Photos
Location Name: Suckla G unit 1
Location ID: 317830



Photo 9 Tank Battery.



Photo 10 Gas Meter run.