

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7322 PAD

Location ID: 316047

Date: 07/31/2025



Photo # 1010 Entrance to location



Photo # 1019 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7322 PAD

Location ID: 316047

Date: 07/31/2025



Photo # 1012 Location



Photo # 1018 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7322 PAD

Location ID: 316047

Date: 07/31/2025



Photo # 1033 NW corner of location



Photo # 1034 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7322 PAD

Location ID: 316047

Date: 07/31/2025



Photo # 1035 SE corner of location



Photo # 1036 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7322 PAD

Location ID: 316047

Date: 07/31/2025



Photo # 1015 Wellhead sign lacks required information

