

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7323 PAD

Location ID: 316048

Date: 07/31/2025



Photo # 1052 Entrance to location



Photo # 1063 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7323 PAD

Location ID: 316048

Date: 07/31/2025



Photo # 1053 Location



Photo # 1061 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7323 PAD

Location ID: 316048

Date: 07/31/2025



Photo # 1072 NE corner of location



Photo # 1073 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7323 PAD

Location ID: 316048

Date: 07/31/2025



Photo # 1074 SW corner of location



Photo # 1075 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7323 PAD

Location ID: 316048

Date: 07/31/2025



Photo # 1057 Wellhead sign lacks required information

