

Final Reclamation and Stormwater Inspection

July 30, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 331935

Well Name: PURITAN #34-34

Inspection Document #: 718600832

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PURITAN #34-34
Location ID: 331935



Photo 1. Looking southwest across the location. The fencing has been removed and the excavations filled.



Photo 2. Looking south across the location. Vegetation on the location is primarily weedy species such as kochia and list C noxious weed cheatgrass. Some desirable vegetation is present. Vegetation on location is reflective of the surrounding area. This location appears to have undergone a land use change to construction material storage/ dumping,



Inspection Photos
Location Name: PURITAN #34-34
Location ID: 331935



Photo 3. Looking west from the wellbore area. See photo 2 comments.



Photo 4. Looking north from the wellbore area. See photo 2 comments.

Inspection Photos
Location Name: PURITAN #34-34
Location ID: 331935




Photo 5. Google earth aerial image taken 09/2021. It appears that reclamation work was conducted on portions of the access road and well location. The entirety of the well location and access road are located in a parcel that appears to be a land use change from cropland to construction.

