

Final Reclamation and Stormwater Inspection

July 30, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 302888

Well Name: ROLOFF-USX UU #9-7

Inspection Document #: 718600836

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROLOFF-USX UU #9-7
Location ID: 302888



Photo 1. Looking southwest down the access road. The access road has been removed. Vegetation on the access road is primarily undesirable weeds such as kochia and list C noxious weed field bindweed.



Photo 2. Looking west across the wellbore area. The wellbore area appears to have lower vegetative coverage than the surrounding area. There is little to no establishment of desirable perennial species. Vegetation on the location is primarily undesirable weed kochia.



Inspection Photos
Location Name: ROLOFF-USX UU #9-7
Location ID: 302888



Photo 3. Looking south from the wellbore. See photo 2 comments.



Photo 4. Looking east from the wellbore. See photo 2 comments.



Inspection Photos
Location Name: ROLOFF-USX UU #9-7
Location ID: 302888



Photo 5. Looking north from the wellbore. See photo 2 comments.



Photo 6. Reference area to the south of the wellbore. Reference area is relatively poor. Reference area consists of vegetation such as sweet clover, alfalfa, field bindweed and kochia.

