

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Aug 1, 2025 at 10:21:20 AM
+39.817266,-108.769652 ±2.65m
Rangely



Aug 1, 2025 at 10:33:39 AM
+39.817167,-108.770098 ±4.96m

Photo # 1143 Entrance to location

Photo # 1151 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1144 Location



Photo # 1145 Wellhead sign lacks required information

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1147 Location



Photo # 1170 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1171 NW corner of location



Photo # 1172 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1173 SE corner of location



Photo # 1160 Tank lacks required labeling

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1166 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 1174 Improperly marked deadman

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #6 PAD

Location ID: 314294

Date: 08/1/2025



Photo # 1175 Improperly marked deadman



Photo # 1176 Improperly marked deadman