

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 1 Location over grown with new vegetation on top of the dead vegetation from previous FIR.

Photo 2 Tank battery, the berm area is over grown with new vegetation on top of the dead vegetation from previous FIR.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 3 Tank battery sign.

Photo 4 Produced water tank over grown with new vegetation on top of the dead vegetation from previous FIR.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 5 Flow line over grown with new vegetation on top of the dead vegetation from previous FIR.

Photo 6 Flow line over grown with new vegetation on top of the dead vegetation from previous FIR.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 7 Vertical Separator over grown with new vegetation on top of the dead vegetation.

Photo 8 Gas Meter Run not currently calibrated & over grown with new vegetation on top of the dead vegetation.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 9 Horizontal Heated Separator over grown with new vegetation on top of the dead vegetation.

Photo 10 Horizontal Heated Separator over grown with new vegetation on top of the dead vegetation.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 11 Wellsite.

Photo 12 Wellhead.

Inspection Photos
Location Name: Martin T. Hart F Unit 1
Location ID: 318222



Photo 13 Wellsite sign.

Photo 14 Ancillary equipment.