



WELL SITE INSPECTION FORM

SCANNED



WELL NAME Jesse #1
OPERATOR Skaer Enterp.
LOCATION NE SW 22-2N-54W
FIELD _____

API NUMBER 05 - 121 - 06934
PERMIT NUMBER _____
COUNTY Washington
INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) Y FAIL(N) _____ DATE 8-4-88 FN _____ FD WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 5-27-88 DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES NO _____ PITS BACKFILLED: YES NO _____

MATERIAL BURIED: YES NO _____ NA _____ SITE CLEAN: YES NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO

DATE OF SAFETY/STATUS INSPECTION 8-4-88 second try

COMMENTS Grass covered at NESW. Pumpjack in vicinity
Seems the recent location should be identified
easier, this one is questionable due older vegetation.