

Inspection Photos

August 6th, 2025

Operator: Abundance Energy Services

Location ID: 325118

Inspection Document #: 714002362

La Plata County, CO

Township: NWSE 21 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118

August 6, 2025
51° NE



Photo 1. View of the project area taken from the access point facing center.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118

August 6, 2025
4° N



Photo 2. “Arkoma Operations” listed on produced water tank. Update tank label to reflect current operator.

Inspection Photos
Location Name: Crigler MVRD Unit 1
Location ID: 325118



Photo 3. New stormwater BMPs installed on southern cut slope, appear to be functioning at this time.

August 6, 2025
325° NW



Photo 4. View of northern cut slope with perimeter stormwater BMPs. Operator appears to have seeded recently, no germination of vegetation was observed. Area remains with loose, bare soils.