

Inspection Photos

Location Name: ZIGGY USX AB/19-99HZ

Location #: 416737



Photo #1

Ziggy USX AB 19-99HZ (123-31474) Wellsite

Producing | PR

Corrective Guidance: Needs Weed Housekeeping



Photo #2

Ziggy USX AB 19-99HZ Battery site

Active

Equipment Documented; Loc ID: 416737



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: ZIGGY USX AB/19-99HZ

Location #: 416737



Photo #3

Ziggy USX AB 19-99HZ Wellsite

Producing | PR

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources