

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1186 Entrance to location



Photo # 1188 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1189 Location



Photo # 1239 NW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1240 SW corner of location



Photo # 1241 SE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1242 NE corner of location



Photo # 1200 Open hole near wellhead/wildlife hazard/personnel safety hazard

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1201 Stockpiled soils with no BMP's



Photo # 1215 Stockpiled soils with no BMP's

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1216 Stockpiled soils with no BMP's



Photo # 1217 Stockpiled soils with no BMP's from other side

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



**Photo # 1219 Tunnel erosion on south side of location is a wildlife hazard/personnel safety hazard**



**Photo # 1224 Berms on location need maintenance**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1225 Berms on location need maintenance



Photo # 1229 Berms on location need maintenance

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1231 Berms on location need maintenance



Photo # 1234 Berms on location need maintenance

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1238 Berms on location need maintenance



Photo # 1211 Chemical tank label is weathered/not legible

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



Photo # 1249 Debris



Photo # 1250 Debris

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #4 PAD

Location ID: 314295

Date: 08/4/2025



**Photo # 1251 Debris**