

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1385 Entrance to location

Photo # 1386 Sign at entrance to location contains inaccurate emergency contact number

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1403 Battery sign lacks nearest public road information



Photo # 1387 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1391 Wellhead sign lacks required information



Photo # 1400 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1429 SE corner of location



Photo # 1430 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1431 NW corner of location



Photo # 1432 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1422 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 1437 Loose barbed wire fencing/wildlife hazard

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1439 Loose barbed wire fencing/wildlife hazard



Photo # 1441 Loose barbed wire fencing/wildlife hazard

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1442 Loose barbed wire fencing/wildlife hazard



Photo # 1443 Loose barbed wire fencing/wildlife hazard

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1409 Chemical tank label is weathered and peeling

Photo # 1428 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #17-15 PAD

Location ID: 316075

Date: 08/6/2025



Photo # 1445 Debris