

Inspection Photos
Location Name: UPRR 23 PAN AM B2
Location ID: 319928



Photo #1 Tanks.

Photo #2 Tanks.

Inspection Photos
Location Name: UPRR 23 PAN AM B2
Location ID: 319928



Photo #3 Meter & separator.

Photo #4 Well head.