

Inspection Photos

July 23rd, 2025

Operator: Neuhaus Properties

Location ID: 378706

Inspection Document #: 714002330

Archuleta County, CO

Township: NENW 18 34N 1E N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Blue Creek Federal 18-1

Location ID: 378706



Photo 1. View of location from the northern edge facing center.



Inspection Photos

Location Name: Blue Creek Federal 18-1

Location ID: 378706



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos

Location Name: Blue Creek Federal 18-1

Location ID: 378706



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: area is dominated by Mullein and Musk Thistle.

Inspection Photos

Location Name: Blue Creek Federal 18-1

Location ID: 378706



Photo 4. Reference area composed predominantly of Smooth Brome.

