

Inspection Photos

08/5/2025

Operator: CAERUS WASHCO LLC - 86610

Location ID: 335016

Inspection Doc: 718100722

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS WASHCO LLC - 86610

Location ID: 335016



Photo 1: Photos taken from the southwest corner of the Location, facing north and east. Photos examples showing Location has not met ECMC 1003.c.(2) desirable vegetative cover requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS WASHCO LLC - 86610

Location ID: 335016



Photo 2: Photo taken from the southwest corner of the Location, facing northeast. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS WASHCO LLC - 86610

Location ID: 335016



Photo 3: Photos taken from the southwest corner of the former pad area, facing east and north. Photos examples showing Location has not met ECMC 1003.c.(2) desirable vegetative cover requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS WASHCO LLC - 86610

Location ID: 335016



Photo 4: Photos taken from the adjacent reference for comparison; Location has not met ECMC 1003.c.(2) 80% desirable vegetative cover requirements to that of the adjacent reference areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources