



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#1 sign at wellhead.
Note pump house behind
wellhead.

Aug 1, 2025 10:47:41 AM
40.509894N 106.3848121W
1688 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#2 close up of
Photo #1.





Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#3 Surface of
secondary containment

Note: hydrocarbon
staining.

Aug 1, 2025 10:47:52 AM
40.509894N 106.3848121W
1688 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#4Surface of
secondary containment

Note: hydrocarbon
staining.

Aug 1, 2025 10:47:55 AM
40.509894N 106.3848121W
1688 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#5 piping and penetrations through the secondary containment.

Aug 1, 2025 10:48:01 AM
40.5098353N 106.3847572W
1688 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 1, 2025 10:48:11 AM
40.5098353N 106.3847572W
1688 County Road 11
Coalmont
Jackson County
Colorado

Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#6
Surface of secondary
containment

Note: hydrocarbon
staining.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#7
Surface of secondary
containment and
pumphouse.

Note:open door to
pumphouse to right of
photo and hydrocarbon
staining.

Aug 1, 2025 10:48:40 AM
40.5098398N 106.3847481W
1692 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#8
Surface of secondary
containment

Note: hydrocarbon
staining.

Aug 1, 2025 10:48:50 AM
40.5098398N 106.3847481W
1692 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#9

Surface of secondary
containment

Note: hydrocarbon
staining.

Aug 1, 2025 10:49:16 AM
40.5098362N 106.3847602W
1691 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#10
Close up of salt
observable inside
secondary containment.

Aug 1, 2025 10:49:40 AM
40.509833N 106.3847568W
1692 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#11

Close up of salt
observable inside
secondary containment.

Aug 1, 2025 10:49:52 AM
40.509833N 106.3847568W
1692 County Road 11
Coalmont
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 1, 2025 10:49:59 AM
40.509833N 106.3847568W
1692 County Road 11
Coalmont
Jackson County
Colorado

Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#12

Surface of secondary
containment

Note: hydrocarbon
staining.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 1, 2025 10:50:16 AM
40.509854N 106.3847172W
1692 County Road 11
Coalmont
Jackson County
Colorado

Inspection Photos
Spill # 491019

Inspection Date: 8/1/2025

Photo#13

Western perimeter of
secondary containment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources