

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 242-1 Production Pad 476159

Location ID: 476160



Photo # 9700 From entrance to location



Photo # 9701 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 242-1 Production Pad 476159

Location ID: 476160



Photo # 9702 Location

Photo # 9703 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC GM 242-1 Production Pad 476159

Location ID: 476160



Photo # 9704 Open ended load line