

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CHANCELLOR-FEDERAL #20-2 PAD

Location ID: 315247

Date: 08/6/2025



Photo # 1451 Entrance to location



Photo # 1454 Wellhead sign lacks required information

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CHANCELLOR-FEDERAL #20-2 PAD

Location ID: 315247

Date: 08/6/2025



Photo # 1460 Location




Photo # 1461 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CHANCELLOR-FEDERAL #20-2 PAD

Location ID: 315247

Date: 08/6/2025



Photo # 1470 NE corner of location



Photo # 1471 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP CHANCELLOR-FEDERAL #20-2 PAD

Location ID: 315247

Date: 08/6/2025



Photo # 1472 SW corner of location



Photo # 1473 SE corner of location