

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404137084  
Receive Date:  
03/28/2025

Report taken by:  
Taylor Robinson

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers Phone: (970) 515-1161 Mobile: ( )
Address: P O BOX 173779		
City: DENVER	State: CO	Zip: 80217-3779
Contact Person: Phil Hamlin	Email: Phillip_Hamlin@oxy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 4235 Initial Form 27 Document #: 1982488

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

No Multiple Facilities

Facility Type: LOCATION	Facility ID: 327225	API #: _____	County Name: WELD
Facility Name: HSR-FAUST-63N66W 21SWSW	Latitude: 40.204970	Longitude: -104.789280	
	** correct Lat/Long if needed: Latitude: 40.205604	Longitude: -104.786186	
QtrQtr: SWSW	Sec: 21	Twp: 3N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use Surface Water and Agriculture  
Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes  
Is groundwater less than 20 feet below ground surface? Yes

**Other Potential Receptors within 1/4 mile**

Surface water approximately 50 feet (ft) east and groundwater approximately 3 ft below ground surface (bgs).

**SITE INVESTIGATION PLAN**

**TYPE OF WASTE:**

- E&P Waste
- Other E&P Waste
- Non-E&P Waste
- Produced Water
- Workover Fluids
- Oil
- Tank Bottoms
- Condensate
- Pigging Waste
- Drilling Fluids
- Rig Wash
- Drill Cuttings
- Spent Filters
- Pit Bottoms
- Other (as described by EPA)

**DESCRIPTION OF IMPACT**

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater Sampling/Laboratory Analysis
Yes	SOILS	75' N-S x 40' E-W x 8' bgs (max)	Soil Sampling/Laboratory Analysis

**INITIAL ACTION SUMMARY**

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In February 2008, petroleum hydrocarbon impacted soil was encountered while field crews were tying new wells into the HSR-Faust 13-21A, HSR-Poe 12 -21A, HSR-Simons 14-21A tank battery. The release was caused by a hole in the side of the partially-buried produced water sump. The petroleum hydrocarbon impacted soil was excavated.

**PROPOSED SAMPLING PLAN**

**Proposed Soil Sampling**

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

On February 21 and 22, 2008, eight soil samples were collected from the excavation sidewalls and submitted for laboratory analysis of total petroleum hydrocarbons (TPH). Laboratory analytical results indicated that the TPH concentrations were in full compliance with the Energy and Carbon Management Commission (ECMC) allowable level at the time of excavation at the lateral extent of the excavation. The soil samples were not analyzed for benzene, toluene, ethylbenzene, and total xylenes (BTEX) as the samples were collected prior to the April 1, 2009, ECMC rule changes. The excavation footprint is depicted on the Site Map provided as Figure 1. Please refer to the Form 27 submitted to the ECMC on May 14, 2008, for additional details.

**Proposed Groundwater Sampling**

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

On February 21, 2008, one groundwater sample (GW01) was collected from the open excavation for laboratory analysis of BTEX. Laboratory analytical results for groundwater sample GW01 indicated that the benzene concentration exceeded the applicable ECMC allowable level at the time of sampling. The excavation groundwater sample location is depicted on Figure 1. The groundwater sample analytical results are summarized in Table 1.

Groundwater monitoring has been performed on a quarterly basis since May 2008.

**Proposed Surface Water Sampling**

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

On February 22, 2008, two surface water samples were collected from the irrigation ditch and submitted for laboratory analysis of BTEX. The laboratory analytical results indicated the surface water samples were less than the laboratory reporting limit of 1.0 µg/L for BTEX. Please refer to the Form 27 submitted to the ECMC on May 14, 2008, for additional details.

**Additional Investigative Actions**

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

[Empty box for additional alternative investigative actions]

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 8

Number of soil samples exceeding 915-1 0

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 2175

### NA / ND

-- Highest concentration of TPH (mg/kg) 870

NA Highest concentration of SAR           

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 4

### Groundwater

Number of groundwater samples collected 466

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 5

Number of groundwater monitoring wells installed 14

Number of groundwater samples exceeding 915-1 73

-- Highest concentration of Benzene (µg/l) 1700

-- Highest concentration of Toluene (µg/l) 220

-- Highest concentration of Ethylbenzene (µg/l) 140

-- Highest concentration of Xylene (µg/l) 410

NA Highest concentration of Methane (mg/l)           

### Surface Water

2 Number of surface water samples collected

0 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)           

Volume of liquid waste (barrels)           

Is further site investigation required?

Per the general comment issued by the ECMC for denied Form 27 Supplemental 404077742, a soil assessment will be conducted to evaluate soil in the 2008 release area for full list Table 915-1 parameters.

Remedial alternatives will be evaluated following the completion of soil assessment activities.

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

### SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Approximately 415 cubic yards of petroleum hydrocarbon impacted soil were removed from the excavation and transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado, for recycling. The impacted soil was excavated into the capillary and phreatic zones to address potential hydrocarbon impacts that may have been present below the groundwater table due to past seasonal fluctuations. The general site layout and excavation footprint are depicted on the Site Map attached as Figure 1.

### REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Prior to backfilling, ten gallons of MicroBlaze®, a concentrated solution of facultative microbes, nutrients, and surfactants designed to bioremediate petroleum hydrocarbons, were applied to the groundwater and exposed smear zone soil in the open excavation. Additional remedial options are under evaluation.

Per the general comment issued by the ECMC for denied Form 27 Supplemental 404077742, a soil assessment will be conducted to evaluate soil in the 2008 release area for full list Table 915-1 parameters.

Remedial alternatives will be evaluated following the completion of soil assessment activities. A standalone implementation schedule is attached.

### Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation ( or enhanced bioremediation )	Yes	Excavate and offsite disposal
_____ Chemical oxidation		If Yes: Estimated Volume (Cubic Yards) _____ 415
_____ Air sparge / Soil vapor extraction		Name of Licensed Disposal Facility or ECMC Facility ID # _____ 149007
_____ Natural Attenuation	No	Excavate and onsite remediation
_____ Other _____		_____ Land Treatment
		_____ Bioremediation (or enhanced bioremediation)
		_____ Chemical oxidation
		_____ Other _____

### Groundwater Remediation Summary

Yes \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
No \_\_\_\_\_ Chemical oxidation  
No \_\_\_\_\_ Air sparge / Soil vapor extraction  
Yes \_\_\_\_\_ Natural Attenuation  
Yes \_\_\_\_\_ Other \_\_\_\_\_ MicroBlaze® Application

### GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater monitoring wells MW01 through MW04, MW07, and MW11 through MW14 are sampled on a quarterly basis for Table 915-1 organic constituents in groundwater. On May 9, 2023, the ECMC approved Kerr-McGee's request to remove the inorganic constituents in Table 915-1 from the ongoing quarterly monitoring program. On March 28, 2024, the ECMC approved the request to remove monitoring wells MW08 through MW10 from the quarterly monitoring program. The monitoring well locations are depicted on Figure 1. The Groundwater Elevation Contour Map generated using the January 2025 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical reports for the February 2024, May 2024, August 2024, November 2024, and January 2025 groundwater monitoring events are attached.

Groundwater monitoring for Table 915-1 organic constituents will continue on a quarterly basis until a No Further Action status request is warranted.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly  Semi-Annually  Annually  Other \_\_\_\_\_

### Request Alternative Reporting Schedule:

Semi-Annually  Annually  Other \_\_\_\_\_

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:  Groundwater Monitoring  Land Treatment Progress Report  O&M Report  
 Other \_\_\_\_\_

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

KMOG has sufficient insurance and bonding to fully address the anticipated costs of Remediation, including the remaining estimated costs for this project. KMOG currently has over 40 million in bonds with the ECMC. The cost for remediation is a preliminary estimate only, costs may change upwards or downward based on site-specific information. KMOG makes no representation or guarantees as to the accuracy of the preliminary estimate.

Operator anticipates the remaining cost for this project to be: \$ 45000 \_\_\_\_\_

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

The petroleum hydrocarbon impacted soil was transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado, for recycling.

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_ 415

E&P waste (solid) description \_\_\_\_\_ Petroleum hydrocarbon impacted soil

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_ 149007

Non-ECMC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_ 0

E&P waste (liquid) description \_\_\_\_\_

ECMC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-ECMC Disposal Facility: \_\_\_\_\_

## REMEDIATION COMPLETION REPORT

### REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No \_\_\_\_\_

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No \_\_\_\_\_

Does the previous reply indicate consideration of background concentrations? \_\_\_\_\_

Does Groundwater meet Table 915-1 standards? No \_\_\_\_\_

Is additional groundwater monitoring to be conducted? Yes

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site was restored to its pre-release grade. The Kerr-McGee production facility remains at the site.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. \_\_\_\_\_

Proposed date of completion of Reclamation. \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/14/2008

Actual Spill or Release date, or date of discovery. 02/14/2008

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/21/2008

Proposed site investigation commencement. 02/21/2008

Proposed completion of site investigation. 12/31/2025

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 02/21/2008

Proposed date of completion of Remediation. 12/31/2026

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

\_\_\_\_\_

**OPERATOR COMMENT**

Per the general comment for denied Form 27 Supplemental Document No. 404077742, this form is being submitted as a replacement within 30 days of receipt of the email notification that the previous form was denied (received March 10, 2025).

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin

Title: Senior Environmental Rep.

Submit Date: 03/28/2025

Email: Phillip\_Hamlin@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

Remediation Project Number: 4235

**COA Type****Description**

0 COA	
-------	--

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

404137084	FORM 27 DENIED
404137096	IMPLEMENTATION SCHEDULE
404137097	ANALYTICAL RESULTS
404137098	ANALYTICAL RESULTS
404137099	ANALYTICAL RESULTS
404137101	ANALYTICAL RESULTS
404137102	ANALYTICAL RESULTS
404137103	ANALYTICAL RESULTS
404137104	SITE MAP
404137105	GROUND WATER ELEVATION MAP
404313113	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 11 Files

**General Comments****User Group****Comment****Comment Date**

Environmental	This form is denied because one or more of the attached laboratory analytical reports is not secured. ECMC has not reviewed this form or any other attachments on this Form. Operator shall resubmit the Form 27 and ensure all laboratory reports are secured and contain metadata appropriate to document any differences in created and modified dates, and/or the laboratory analytical report shall be signed with a validated signature certificate.	08/12/2025
---------------	--	------------

Total: 1 comment(s)