

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 06/04/2025 Document Number: 404228468

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 75000 Contact Person: April Pryor Company Name: BYRD\* CAROL W TRUSTEE OF CAROL W BYRD TRUST Phone: (405) 379-2600 Address: 8163 E 131 RD Fax: ( ) City: WETUMKA State: OK Zip: 74883-6227 Email: april@oilandgasroyalties.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102612 Initial Form 19 or 27 Document number: Facility Name: LYLE CHANDLER Facility Number: Facility Type: PIT Location QtrQtr: NESE Section: 10 Township: 2N Range: 49W Meridian: 6 County: WASHINGTON Field Name: HYDE Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc Agent Name: Lauren Glazer Title: Consultant Phone Number: 800-288-2657 Email: lglazier@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 03/27/2025 On inspection the Pit was: [X] Unlined [ ] Lined [ ] Fenced [ ] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 234894 Facility Name: LYLE CHANDLER 1 Facility Type: Oil and Gas Well Location: QtrQtr: NESE Sec: 10 Twp: 2N Range: 49W Meridian: 6 County Name: WASHINGTON Latitude: 40.154260 Longitude: -102.833370

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 127138 Document Name: EDD File Name: 2025\_0327\_909J\_Lyle Chandler\_CGRS EDD AA19889.xlsx Sample Type: Matrix: Facility ID: 234894 Sample ID: 667768 Sample Name: Lyle Chandler 1 Sample Date: 03/27/2025 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample Project Number: 1420 Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Elevation Diagnostics Lab Sample ID: AA19889

Sample Facility Attachment:

| Facility ID | Attach Num | File Name                                   | Document Name                | File Type |
|-------------|------------|---|------------------------------|-----------|
| 234894      | 404228480  | 2025_0327_909J_Lyle<br>Chandler_AA19889.pdf | Analytical Laboratory Report | PDF       |

**Sample ECMC Well Related:**

| Sample ID | API Num   | Well Name & Num | Sample Reason                |
|-----------|-----------|-----------------|------------------------------|
| 667768    | 121-07036 | LYLE CHANDLER 1 | Rule 909.j subsequent sample |

**General Comments**

| <u>User Group</u>  | <u>Comment</u>  | <u>Comment Date</u> |
|--------------------|---|---------------------|
| Environmental Data | The data submitted by the operator can be accessed through the COGIS data system. | 08/12/2025          |

Total: 1 comment(s)