

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 8/8/2025



Aug 8, 2025 at 11:36:12  
+39.503935,-108.122983



Aug 8, 2025 at 11:37:11  
+39.501514,-108.125600

Location Overview – Photo #00082

Location – Photo #00083

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 8/8/2025



Location – Photo #00090




Location – Photo #00086

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 8/8/2025



Weathered Tank Label – Photo #00087



Hole in Containment Liner – Photo #00089

## Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 8/8/2025



Hole in Containment Liner – Photo #00088



Soil Stockpile on Location with no BMPs Installed – Photo #00085