

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 17-1 PAD

Location ID: 315078

Date: 08/7/2025



Photo # 1488 Entrance to location




Photo # 1503 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 17-1 PAD

Location ID: 315078

Date: 08/7/2025



Photo # 1489 Location



Photo # 1502 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 17-1 PAD

Location ID: 315078

Date: 08/7/2025



Photo # 1514 NE corner of location



Photo # 1515 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 17-1 PAD

Location ID: 315078

Date: 08/7/2025



Photo # 1516 SE corner of location



Photo # 1517 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 17-1 PAD

Location ID: 315078

Date: 08/7/2025



Photo # 1500 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 1522 Debris