

Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685

Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/12/2025 Inspection Doc#: 693808920



Injection wellhead during MIT



Form 21 field copy