

Inspection Photos
Location Name: UPRR 23 PAN AM D#3
Location ID: 319938



Photo#1 Production Tank/**CA:Weeds Throughout location**

Photo#2 Produced Water Concrete Vault/**CA:Weeds Throughout location**

Inspection Photos
Location Name: UPRR 23 PAN AM D#3
Location ID: 319938



Photo#3 Gas Meter/Separator/**CA:Weeds Throughout location**

Photo#4 Wellhead/**CA:Weeds Throughout location**