

Inspection Photos
Location Name: UPRR 23 PAN AM M#2
Location ID: 319982



Photo#1 Production Tanks/Produced Water Vault/CA:Weeds

Photo#2 Gas Meter/Separator

Inspection Photos
Location Name: UPRR 23 PAN AM M#2
Location ID: 319982



Photo#3 Wellhead/CA:Weeds