

Inspection Photos
Location Name: UPRR 23 PAN AM M#3
Location ID: 320062



Photo#1 Wellhead/CA:Weeds

Photo#2 CA:Weeds throughout location

Inspection Photos
Location Name: UPRR 23 PAN AM M#3
Location ID: 320062



Photo#3 Gas Meter/CA:Weeds throughout location

Photo#4 Production Tank/CA:Weeds throughout location