

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Production facility



Wellheads

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Trash at wellheads



Trash at the battery

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Wellhead



Uncovered cellar

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Wellhead



Uncovered cellar

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Weeds



Weeds

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Weeds



Weeds

Inspection Photos
Location Name: Tailholt FD Pad 11-25HN
Location ID: 433845



Energy & Carbon Management Commission
40.50836, -104.86783, 1470.6m, 318°
08/13/2025 09:49:38

Incorrect sign



Energy & Carbon Management Commission
40.50916, -104.86677, 1468.6m, 59°
08/13/2025 09:51:06

Trash