

Inspection Photos

August 12th, 2025

Operator: Simcoe LLC

Location ID: 333662

Inspection Document #: 714002383

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCarville C2, C4
Location ID: 333662

August 12, 2025
319° NW




Photo 1. View of the project area taken from the access point facing center.

August 12, 2025
250° W



Photo 2. Labels at meter house and separator equipment have deteriorated and are no longer legible.



Photo 3. Produced water sign has fallen over and has sun fade; no longer legible.

August 12, 2025
165° S



August 12, 2025
146° SE



Photo 4. Flowering Musk Thistle and thick patches of Kochia and Russian Thistle lining the length of the access road.

August 12, 2025
4° N



Photo 5. Western interim reclamation area.