

Inspection Photos

August 12th, 2025

Operator: Smith LLC

Location ID: 326118

Inspection Document #: 714002386

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

August 12, 2025
57° NE



Photo 1. View of the project area taken from the access point facing center.

Inspection Photos
Location Name: Smith Wolter B1
Location ID: 326118



Photo 2. Stained soils at pump jack muffer.



Inspection Photos
Location Name: Smith Wolter B1
Location ID: 326118



Photo 4. Aerial imagery taken with a drone showing movement of sediment onto location.