

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Photo # 1688 Entrance to location



Photo # 1694 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Photo # 1689 Location



Photo # 1693 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Photo # 1718 SE corner of location



Photo # 1719 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Photo # 1720 NW corner of location



Photo # 1721 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Aug 11, 2025 at 1:28:54 PM
+39.867223,-108.726190 ±24.40m
Rangely



Aug 11, 2025 at 1:29:54 PM
+39.867223,-108.726190 ±24.40m
Rangely

Photo # 1707 Possible leaks on production tank

Photo # 1710 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL 22-4 PAD

Location ID: 316105

Date: 08/11/2025



Photo # 1722 Improperly marked deadman



Photo # 1723 Improperly marked deadman