

Inspection Photos

07/16/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 324291

Inspection Doc: 719200051

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 1: Photo taken from central portion of the Location shows an overview looking south. The well has been plugged, abandoned and marked.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 2: Photo taken from central portion of the Location shows an overview looking southeast. Vegetation is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 3: Photo taken of the Location shows an overview looking west. Vegetation is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 4: Photo taken from central portion of the Location looking north shows unused riser equipment remaining at the Location. Comply with Rule 1004.a. and remove surface equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 5: Photo taken at the beginning and end of the Reference Area transect, respectively. Vegetation at the Location is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 5: Photo taken at the midpoint of the Reference Area transect looking west and east, respectively. Vegetation at the Location is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 6: Photo taken at the beginning and end of the Disturbed Area transect, respectively. Vegetation at the Location is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324291



Photo 6: Photo taken at the midpoint of the Disturbed Area transect looking east and west, respectively. Vegetation at the Location is progressing towards 1004 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources