

WGS84
±8ft

40.78025, -106.26473

m
±3m

2474

°T
±10

SE132



ECMC
Environmental
Field Inspection



McCallum 33 Flowline
03-Jun-25 05:00:57 PM
ECMC Environmental Inspection

Looking towards approximate spill location from access road.

WGS84 $\pm 18\text{ft}$ 40.78010, -106.26455 $\wedge^m_{\pm 5\text{m}}$ 2474 $\triangle^{\circ, T}_{\pm 12}$ SE151



ECMC
Environmental
Field Inspection



McCallum 33 Flowline
© 03-Jun-25 05:01:40 PM
ECMC Environmental Inspection

Looking at approximate spill location.