

Inspection Photos  
Location: MPU Battery Sec. 25  
Location ID: 480642  
Tank Battery: 480641



Photo 1 –Tank Battery placard

Photo 2 – Impacted material under tanks

**Inspection Photos**  
**Location: MPU Battery Sec. 25**  
**Location ID: 480642**  
**Tank Battery: 480641**



**Photo 3 – Excavation within secondary containment**

**Photo 4 – Excavation area June 3, 2025**

**Inspection Photos**  
**Location: MPU Battery Sec. 25**  
**Location ID: 480642**  
**Tank Battery: 480641**



**Photo 5 – Impacted soils stockpiled on the east side of tank battery**



**Photo 6 – Vessel with oil overflowing, impacted soils**