

Inspection Photos

07/30/2025

Operator: Caerus Piceance LLC #10456

Location ID: 398469

Inspection Doc: 719200084

Rio Blanco County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



Photo 1: Photo taken showing an overview of the Location looking east. Bare patches and undesirable plant species appear to be present.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



Photo 2: Photo taken of the access to the Location looking east. The access road has been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



Photo 3: Photos showing an example of Canada thistle growing throughout the Location. Comply with Rules 606.c. and 1004.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources