

Inspection Photos  
Location Name: Wingo, C.E. 2  
Location ID: 323256



Photo 1 Location.



Photo 2 Stained soil around the Wellhead.

Inspection Photos  
Location Name: Wingo, C.E. 2  
Location ID: 323256



Photo 3 Wellsite Sign.

Photo 4 Gas engine overrun with tall vegetation.