

Inspection Photos
Location Name: Graham 1
Location ID: 317997



Photo 1 Location overrun with tall vegetation.

Photo 2 Tall vegetation around the Wellhead.

Inspection Photos
Location Name: Graham 1
Location ID: 317997



Photo 3 Wellsite Sign hidden by tall vegetation.



Photo 4 Ancillary equipment overrun with tall vegetation