

Inspection Photos
Location Name: Graham Unit 1
Location ID: 318156



Photo 1 Location overrun with tall vegetation.

Photo 2 Tall vegetation around the Wellhead.

Inspection Photos
Location Name: Graham Unit 1
Location ID: 318156



Photo 3 Well site Sign.

Photo 4 Pump jack overrun with tall vegetation