

Final Reclamation Inspection

July 21, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 410174

Inspection Document #: 718800629

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MARICK #1061-6-43
Location ID: 410174



Photo 1. Photo taken of the abandoned well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance at the location and based on records the well was never drilled.



Photo 2. Photo taken from the abandoned well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MARICK #1061-6-43
Location ID: 410174



Photo 3. Photo taken from the abandoned well location, facing south. See comments under Photo 1.



Photo 4. Photo taken from the abandoned well location, facing west. See comments under Photo 1.