

Final Reclamation Inspection

July 21, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 417562

Inspection Document #: 718800631

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CON GQ 07-03
Location ID: 417562



Photo 1. Photo taken of the abandoned multi-well location, facing north. Photo illustrates that there is no evidence of oil and gas disturbance at the location and based on records no well was drilled.



Photo 2. Photo taken from the abandoned multi-well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: CON GQ 07-03
Location ID: 417562



Photo 3. Photo taken from the abandoned multi-well location, facing south. See comments under Photo 1.



Photo 4. Photo taken from the abandoned multi-well location, facing west. See comments under Photo 1.