

Final Reclamation Inspection

July 23, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 419100

Inspection Document #: 718800665

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RICH #3-28
Location ID: 419100



Photo 1. Photo taken from the well location, facing North. Photo illustrates that vegetation has not established to Rule 1004 standards and subsidence was observed at the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: RICH #3-28
Location ID: 419100



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1. Photo illustrates subsidence that was observed at the location.

Inspection Photos
Location Name: RICH #3-28
Location ID: 419100



Photo 5. Photo taken of ground cover at the well location. Photo illustrates subsidence at the location, highlighted in red.



Photo 6. Photo taken of the well location, facing north. Photo illustrates weedy annual vegetation was observed across the location including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).



Inspection Photos
Location Name: RICH #3-28
Location ID: 419100



Photo 7. Photo taken of the reference area to the location, east of the location, facing south. Photo illustrates rye cropland.

