

Final Reclamation Inspection

July 23, 2025

Operator: BAYSWATER EXPLORATION & PRODUCTION LLC -
10261

Location ID: 419267

Inspection Document #: 718800667

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RICH TANK BATTERY
Location ID: 419267



Photo 1. Photo taken of the tank battery location, facing southwest. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*), was observed across the location.



Photo 2. Photo taken from the tank battery location, facing north. See comments under Photo 1.

Inspection Photos
Location Name: RICH TANK BATTERY
Location ID: 419267



Photo 3. Photo taken from the tank battery location, facing northeast. See comments under Photo 1.



Photo 4. Photo taken of the tank battery location, from the access road to the location, facing northeast. See comments under Photo 1.

Inspection Photos
Location Name: RICH TANK BATTERY
Location ID: 419267



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the tank battery location, east of the location, facing east.