

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK Unit #38 PAD

Location ID: 315835

Date: 08/12/2025



Photo # 1731 Entrance to location



Photo # 1740 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK Unit #38 PAD

Location ID: 315835

Date: 08/12/2025



Photo # 1732 Location



Photo # 1739 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK Unit #38 PAD

Location ID: 315835

Date: 08/12/2025



Photo # 1753 NW corner of location



Photo # 1754 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK Unit #38 PAD

Location ID: 315835

Date: 08/12/2025



Photo # 1755 SE corner of location



Photo # 1756 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK Unit #38 PAD

Location ID: 315835

Date: 08/12/2025



Photo # 1734 Wellhead sign lacks required information

Photo # 1763 Unmarked deadman