

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 9846 From entrance to location




Photo # 9847 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 9848 Location



Photo # 9849 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Aug 12, 2025 at 10:53:12 AM
+39.457228,-107.697390



Aug 12, 2025 at 10:54:24 AM
+39.457404,-107.697292

Photo # 9850 Location

Photo # 9851 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC WAGSTROM 8-13 (M8E) Pad

Location ID: 334800



Photo # 9852 Dead bird in secondary containment



Photo # 9853 Dead bird in secondary containment