

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #I-20-3-101-S PAD

Location ID: 315352

Date: 08/14/2025



Photo # 1846 Entrance to location



Photo # 1859 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #I-20-3-101-S PAD

Location ID: 315352

Date: 08/14/2025



Photo # 1847 Location



Photo # 1848 Wellhead sign lacks required information

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #I-20-3-101-S PAD

Location ID: 315352

Date: 08/14/2025



Photo # 1869 SW corner of location



Photo # 1870 SE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP FEDERAL #I-20-3-101-S PAD

Location ID: 315352

Date: 08/14/2025



Photo # 1871 NE corner of location



Photo # 1872 NW corner of location