Inspection Photos
Location Name: UPRR 42 Pan Am E2
Location ID: 317665

Photo 1 Location access rd.

Photo 2 Wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am E2
Location ID: 317665

Photo 3 Fencing around excavation is down & needs to be repaired.

Photo 4 Wellsite sign.

Inspection Photos
Location Name: UPRR 42 Pan Am E2
Location ID: 317665



Photo 5 Exposed Wellhead, Tall vegetation around the wellsite.

Photo 6 Tall vegetation around the wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am E2
Location ID: 317665

Photo 7 Tall vegetation around the location.

Photo 8 Tall vegetation around & in the contaminated soil pile.

Inspection Photos
Location Name: UPRR 42 Pan Am E2
Location ID: 317665

Photo 7 Tall vegetation around & in contaminated soil pile..