

Inspection Photos
Location Name: Alex H Miller 1
Location ID: 318376



Photo 1 Access road overgrown with vegetation.

Photo 2 Well site, ancillary equipment overrun with tall vegetation.

Inspection Photos
Location Name: Alex H Miller 1
Location ID: 318376



Photo 3 wellsite sign.

Photo 4 Wellhead.