

Inspection Photos
Location Name: Suckla-Brown Unit 12
Location ID: 318307



Photo 1 Access road overgrown with vegetation.



Photo 2 Ancillary equipment overrun with tall vegetation.

Inspection Photos
Location Name: Suckla-Brown Unit 12
Location ID: 318307



Photo 3 Wellsite overgrown with vegetation.

Photo 4 wellhead is overrun with tall vegetation.

Inspection Photos
Location Name: Suckla-Brown Unit 12
Location ID: 318307



Photo 3 Wellsite sign partially hidden with overgrown with vegetation.